ogen

BLACK SHIELD CHECK LIST (as of 14 Jul 67)

Page 2

H-Minus	25X1 ACTION	DOI	RESP INDV	TIME DUE(Z)	TIME DUE(L)	TIME DONE(L)	DONE BY (Initials)
-10:00	(Terminal wx fcsts)	B - 5	B FesTR	13/16/10	14/0110	0110	TY
-9:00	O-NO GO wx fcsts)	8 -1 1	11	1710	0210	0130	TX
-9:00	out to Msn Coord	B-23		1710	0210	0100	TY
-8:00	thru L-hr, if reqd)	B -1 6	B& A FESTAS	1810	0310		
	Annotate tanker DD Forms 175	B -2 4				0610	BUD
25X1	Brief tankers	B-24		2110	0610	0610	STAN
-4:00	Send (Terminal wx fcsts)	B 5		2210	0710	0710	(Am)
-4:00	Send (Met Watch obs)	B -1 8		22/0	0710	0710	(Am)
	Brief tankers	B -2 4		2230	0730	0740	Am
-3:30	Brief pilots and ops staff	3-20		2240	0740	0740	Daß
5X1	Brief tankers	B -2 4		2300		0810	din
-3:00	Rcv Amend (GO/NO GO fosts)	B -11		2310	0810	0722	Dals
-3:00	Rcv Letdown Plates from DCO	B -1 4		2310	0810	0820	DEK
-3:00		E -1 4		2310	0810	0905	Dels
-2:30	Msn Obsvr to CP; posts data	B -1 3		2340	0840	0845	RAP
	25X1Wx Scout reports)	B -2 2		14/0010	0910		
5X1		B -1 0		opoo or ASAP	9000 or ASAP		
-1:40	Msn Festr to CP; Obsvr to wx str			0030	0930	1030	DER
	Letdown plate fests to pilots	E-14		0035		1015	Dels
-1:30	Notify DCOL	B-20		0040	0940		
-1:10		B-20		0000	1000		
	PICK UP APT PICTURES (NIMBE) Landing time: 14/ Z L				-		
+0:15	,	B-13					
+0:15		B-15					
+0:45		B -1 5		· · · · · · · · · · · · · · · · · · ·			
ASAP	Give nput to DCOM Coord	B -1 5		ASAP	ASAP		1
+24:00				HORE	NOAL		
	Turn in Msn Wx File to Intell	B -1 7				AR RE-R	E) (1E) A

25X1

Sanitized Copy Approved for Release 2009/12/22: CIA-RDP69B00041R002300040001-9

BEST COPY Available THROUGHOUT FOLDER

